

# NOTICE TO MARINERS

## No. 16 – 2015

### UPLEES NORTH CARDINAL BUOY DEFECT

NOTICE IS HEREBY GIVEN that the UPLEES NORTH CARDINAL BUOY has sustained a defect resulting in the loss of the top mark section (two triangles). The location of the buoy's position is:-

51° 21.31' N 000° 52.69' E



The UPLEES NORTH CARDINAL BUOY marks a SUNKEN 50 foot fishing trawler lying awash in the small craft moorings adjacent to the "Scrubbing Dock" in the East Swale.

Further information may be obtained from Medway Navigation Service (VTS) on VHF Channel 74, callsign "Medway VTS", or telephone (01795) 663025.

Admiralty Chart No. 2482 refers.

David Newbury

Senior Manager Marine Operations

19<sup>th</sup> May 2015

Telephone calls, VHF radio traffic, CCTV and radar traffic images may be recorded at the VTS Centre at Sheerness

**Port of Sheerness Limited**

Sheerness Docks  
Sheerness  
Kent  
ME12 1RS

T: +44 (0)1795 596 596  
F: +44 (0)1795 660 072  
E: [info@peelports.co.uk](mailto:info@peelports.co.uk)  
W: [www.peelports.com](http://www.peelports.com)

