

NOTICE TO MARINERS

No. 18 – 2015 Update

Sheerness Outfall North Cardinal Buoy Back On Station

NOTICE IS HEREBY GIVEN that the Sheerness Outfall North Cardinal Buoy is back on station, in position;

51° 26.97' N 00° 45.18' E

The Sheerness Outfall North Cardinal Buoy was reported off station on the 26th May 2015 by a passing vessel. The buoy drifted onto the lee shore at Sheerness, where it was subsequently recovered, repaired and returned to its original charted position.

Vigilant reporting of defects and hazards on the River Medway and The Swale is very much appreciated. We hope that this positive reporting and support from river users will be continued.

Further information may be obtained from Medway Navigation Service (VTS) on VHF Channel 74 call sign "Medway VTS" or direct on phone No. 01795 663025.

Admiralty Chart No. 3683 refers.

David Newbury

29th May 2015

Senior Manager Marine Operations

Telephone calls, VHF radio traffic, CCTV and radar traffic images may be recorded at the VTS Centre at Sheerness

Port of Sheerness Limited
Sheerness Docks
Sheerness
Kent
ME12 1RS

T: +44 (0)1795 596 596
F: +44 (0)1795 660 072
E: info@peelports.co.uk
W: www.peelports.com

